

14-98

N^o 6080


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-8-53IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 169SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH84' 9' DeepWAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Harry Urban + Ring

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/17/53

REMARKS:

№ 6080

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/6 1920

RECEIVED OF Anthony J. J. J. J. FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED to

TO TAP San SEWER, ON THE W

OF 2325 7th AVE., TYPE OF STREET W. C. S.
ST.,

THE PREMISES BEING LOT NO. 3721, HOUSE NO. 167

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban & Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.