

6-21

Nº 6085


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-25-53IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1505SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH47'6' DEEPWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Urban & Pingley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

LeRoy K. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-5-53

REMARKS: _____

NO 6085

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/24/53 19

RECEIVED OF E. E. Mize FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED E. E. Mize

TO TAP Sanitary SEWER, ON THE southwest corner SIDE

OF Walnut S. W. AVE., TYPE OF STREET hard surface

THE PREMISES BEING LOT NO. 8842, HOUSE NO. 1505

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Arthur R. Ringley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.