Nº 6088

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $9-9-5$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2425	<u>.</u>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6.5 De
WAS LATERAL AT CURBY YES	and the second of the second o	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MARGON &	Ringley
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
- 10 m		
	The state of the s	
	(6)	deep
	and the state of the control of the	
	· · · · · · · · · · · · · · · · · · ·	
\mathcal{J}		\ lup
		15 (13
SIGNED SHOY LON	FILED AT ENGINEER'S OFFICE	16/16/1
INSPECTOR FOR C	ITY	171-53 /-

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6088 PERMIT TO TAP SEWER

and the company of the second
MASSILLON, OHIO,
1 to the last the las
RECEIVED OF THE OF S
and the control of th
FOR WHICH PERMISSION IS GRANTED
TO TAPSEWER, ON THE
OFAVE TYPE OF STREET
THE PREMISES BEING LOT NO. 7 3/4 , HOUSE NO. 2425

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.