


Nº 6091

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-17-53IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1128SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 37'6' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN 146NAME OF CONTRACTOR Glenn

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ernest Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-21-53

REMARKS: _____

Nº 6091

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/14 1918

RECEIVED OF

Charles M. Allen

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

Same

SEWER, ON THE

W

OF

Stratford St.

AVE.

TYPE OF STREET

Pine St.

THE PREMISES BEING LOT NO.

10620 - 21

HOUSE NO.

1128

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Hann

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.