Nº 6096

REMARKS:

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-15-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1507	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH TOPPE MAL. 1/ Depth
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Wiana
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	The state of the s
	3
	The wide
	The second of the second secon
SIGNED KNOY XOIT	Kam FILED AT ENGINEER'S OFFICE Tap
INSPECTION FOR CIT	

Nº 6996

PERMIT TO TAP SEWER

	MASSILLON, OHIO, Sept 18 19
	RECEIVED OF 9. Deand FEE OF \$ 2.0
	FOR WHICH PERMISSION IS GRANTED Jamo onas
	TO TAP familiary SEWER, ON THE Just
	of Wales Rol M C AVE. TYPE OF STREET to Some
1	THE PREMISES BEING LOT NO. 8397 , HOUSE NO. 1507
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	NAME OF CONTRACTOR (1. C) Klima

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.