Nº 6099

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-12-53	IF SO HOW AND LOCATION FROM	
HOUSE NO. 608	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED# "	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	in M.H.
WAS LATERAL AT CURB? NO.	and the second of the second o	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIAMA	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	1
on the open and the substitute of the control of the second section of the section of the second section of the second section of the second section of the secti		
		V
original de la companya de la companya de la Principal de la companya de la Principal de la companya de la Principal de la companya de la com	or Used. II' 6' Deep	Ŋ
Conn	ected in Mith.	·
	7 2 Deep	Main Sewer
0 1		Alley
SIGNED KIJ, Grandel	FILED AT ENGINEER'S OFFICE	12-21-53
INSPECTOR FOR CIT	section of the color follows in a fine of the color	1
REMARKS: 4" STUD 1	n M. H.	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 6099 PERMIT TO TAP SEWER

	no o describirante de la Mas Contrata de Mas	sillon, Ohio,	9.16-53 19
RECEIVED OF O	Deama	•	FEE OF \$
FOR WHICH PERMISSION IS GRANT	TED Zhordi	u Mont	-n (
TO TAP Sanitam	SEWER, ON T	HE roll	1
of Males 41	AVE. TYPE OF S	STREET C	led
THE PREMISES BEING LOT NO		, HOUSE NO	605
Work to be done in accordan	ICE WITH ORDINANCE NO.	2323. DULY PASSE	D BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PU			

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.