## Nº 6106

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-17-5-3	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	3'00
WAS LATERAL AT CURB? YES	and the second of the second o	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	<u>noi</u>
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
		diep.
	1 3d	el)
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE 12-2	lar for a
REMARKS:		

## Nº 6106

## PERMIT TO TAP SEWER

Massillon, Ohio, 9	5 - 5 3 <sub>10</sub>
RECEIVED OF 71 1 Lacense	FEE OF S 0 - 0
FOR WHICH PERMISSION IS GRANTED Per In atrice	
TO TAP SEWER, ON THE BOLL	A
of Wilden IC AVE. TYPE OF STREET ALLE	2. 1. 1. 1. 1. 1. 1
	3/
Work to be done in accordance with Ordinance No. 2323, Duly passed a	BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR A LOCAL	4
- <b>1</b>	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.