

N^o 6114

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.**

DATE INSPECTED 9-24-53 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 833

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 79'
CURB LINE AND DEPTH 7' deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN no NAME OF CONTRACTOR Diario

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-21-53

REMARKS:

Nº 6114

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7-22-53 19

RECEIVED OF A. J. Diana FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Karl Oser

TO TAP Sanitary Sewer SEWER, ON THE South
OF Franklin N.E. AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT NO. 8031, HOUSE NO. 833

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Diana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.