## Vº 6123

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

 DATE INSPECTED 5-15-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 173		
 SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	9' Norr
WAS LATERAL AT CURBY YES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Pey
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
		121
Λ/		Colup
<u> </u>		
•	7	a'de
		1/21
SIGNED ANOY date	FILED AT ENGINEER'S OFFICE	1_ 2 2
INSPECTOR FOR CIT	an the character of positions in Com-	5750
REMARKS:		

## Nº 6123

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-4-53 11			
RECEIVED OF Ray Remly FEE OF \$ 2.			
7 1 0			
FOR WHICH PERMISSION IS GRANTED 7100 CONTROL			
TO TAP SEWER, ON THE			
of 23 al Now AVE. TYPE OF STREET Orled			
THE PREMISES BEING LOT NO. 3719, HOUSE NO. 173			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Ray Remly			
TAME OF CONTRACTOR AS A STATE OF CONTRACTOR AS			

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.