## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6134 AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-3/-5	IF 50 HOW AND LOCATION FROM	
	FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6 10'DE
WAS LATERAL AT CURBY Y-CS	para karangan Alimangan dan karangan dan dalah	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	R Rember
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVE	ΞĎ. //
		· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·	<u>/'</u>
and a substitution of the state	i de <u>la Marakan Illin iliji de principala sa</u> kababasa bal Marakan	16 dup
	ente i la companya di salah da salah d	An area and a second of the se
		11 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -
		In in all
	and the second section of the s	Transfer Tuber
My Kyord Kort	Acers	The second secon
SIGNED / INSPECTOR FOR	R CITY	IEER'S OFFICE
REMARKS:	All artikenik od trojdersi polik	and the state of
MEMANCO:		

15-26

## Nº 6134

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	and the second s	1 T. T.	Massillon, O	ню, //-	6-53
RECEIVED OF	Ray Re	nly		4	FEE OF S
FOR WHICH PERMISS	ION IS GRANTED	، . و -	Bak	٠	and far the only the
TO TAP COM	tou	SEWER, C	ON THE	w	
of 16 C4	SE NOR	te a final e	OF STREET	ocli	
THE PREMISES BEING	1000	305		5E NO	343
WORK TO BE DONE	IN ACCORDANCE WITH				
RULES OF THE DEPAR	TMENT OF PUBLIC SERV	/ICE.		•	

NAME OF CONTRACTOR ROLL

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.