

Nº 6158

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-31-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 837

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes

26' 6 1/2' Deep

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House foundation not laid
out when inspection was made.

Approx S. Curb
Line



SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 6158

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12-31-53 15

RECEIVED OF

A. J. Davis

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Carl Osce

TO TAP

San.

SEWER, ON THE

East

OF

Franklin NE

AVE.,
ST.,

TYPE OF STREET

Quit

THE PREMISES BEING LOT NO.

8032

HOUSE NO.

837

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Davis

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.