FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
Lumber	
	5.15.1
SIGNED INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE 2-20-54

Nº 6159

PERMIT TO TAP SEWER

, ,	ere a compe			2-31-53 15
		MASSI	LLON, OHIO,	<u>0 </u>
RECEIVED OF	2.9 De	8~~		FEE OF S Q .
FOR WHICH PERMISSION IS	GRANTED	P. 7 X	eynold	
			1	/
OF & Dixta Y). E. ^	VE TYPE OF ST		med
THE PREMISES BEING LOT N	161-		, HOUSE NO	1436
WORK TO BE DONE IN ACC		the state of the s	323, DULY PASSE	ED BY THE CITY COUNCI
NAME OF CONTRACTOR	(a. Q.	Oim		

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.