

Mildred here it is.  
See me if not clear Dick

15-10

Nº 6164

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-1-51

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 930

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

47'

6' Deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

R. P. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 6164

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

Feb 2

19

RECEIVED OF

Ray Rensley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

E. W. Hansen

TO TAP

Lariton

SEWER, ON THE

east

OF

Cherry Rd NW

AVE.  
ST.,

TYPE OF STREET

oiled

THE PREMISES BEING LOT NO.

P 70.2 S 3

HOUSE NO.

930

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Rensley

Note. This permit covers work outside of building only. Any work in  
walls of building is subject to Massillon Board of Health Regulations.