## Nº 6172

## 6172 AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-/7-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·
HOUSE NO. ///4		
SIZE OF PIPE USED	UP DISTANCE FROM FIRST MANHOLE 131	8' L
WAS LATERAL AT CURBY YES	<ul> <li>Additional Control of the Company Report of the Com</li></ul>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A Dean	<i>-</i> q
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
	The state of the s	15/600
$\leftarrow \sim$		
ere amb our de eren our parables baren bratainet.	and the same and the second of	3/
	<ul> <li>[1] A. M. W. W.</li></ul>	٥٤١
		2
Q 1-		
SIGNED loyeath	FILED AT ENGINEER'S OFFICE 137	-
/ INSPECTOR FO	or city The day of the p. M. of the following of purilible of the attention of the city.	3-29-
REMARKS:		• •

## Nº 6172

## PERMIT TO TAP SEWER

MASSILLON, OHIO. 3/16/5-4
RECEIVED OF Q. Wiana FEE OF S 2
FOR WHICH PERMISSION IS GRANTED James Carley In.
TO TAP Lantan SEWER, ON THE Last
OF MAN MAYE. TYPE OF STREET DILA
THE PREMISES BEING LOT NO. 8252 , HOUSE NO. 1/14
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.

