

SR 9-:

Nº 6174


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-23-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 2229SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
35' upstream 7' D.
CURE LINE AND DEPTHWAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Ringley Union

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

35'
3/29/54 JS

Nº 6174

9-27
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/20/54 1E
RECEIVED OF George Hastler FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Wm. Hays

TO TAP

Sanitary

SEWER, ON THE

South

OF

Tremont Ave

AVE.,
ST.,

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

10334

HOUSE NO.

2229

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.