


6-33

Nº 6180

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-2-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1670SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 276' 4' DeepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NoNAME OF CONTRACTOR Urban & Ringler

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 6180

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

Mar 27

19

RECEIVED OF

Urban & Ringley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Robert Rosa

TO TAP

San

SEWER, ON THE

E

OF

County N E

AVE.,
ST.,

TYPE OF STREET

oiled

THE PREMISES BEING LOT NO.

10857852

HOUSE NO.

1670

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.