Nº 6182

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-1-54	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 836	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 70 8 DEEP.
WAS LATERAL AT CURB? Yes	en en en <mark>de la financia de la composición de la composición de la composición de la composición de la financia</mark> La composición de la
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BOGEN
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	6 Deep
egen politica a li terro Pipoletini kisala alianga a li subdividu in tro s	8, £-18, Deen
	16' Approx. N. Cuil)-mi
	J. S. Main Se
SIGNED R. F. Angle	FILED AT ENGINEER'S DEFICE 5-8-54
REMARKS:	A - Harris - English and political traditions

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	or and the constitute of the c	to the state of th	sillon, Ohio,	mar 3	15
RECEIVED OF	Duane	Boger		FEE C	of \$ 2.
FOR WHICH PERMISS	ON IS GRANTED	11.11.	Planke	#	
то тар	n.	SEWER, ON T	HE	E.	
or Frankl	En au 17. E	AVE. TYPE OF S		Oiled	
THE PREMISES BEING		_;•••			
WORK TO BE DONE	N ACCORDANCE WITH	ORDINANCE No.	2323, DULY PA	SSED BY THE C	ITY COUNCI

This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.