

Nº 6199

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-5-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1929SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 80' 7' DEEPWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NONAME OF CONTRACTOR Albrecht

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

West
Curb

7' Deep 90°

34'

13' 7' Deep

SIGNED Roy Latham
INSPECTOR FOR CITYFILED AT ENGINEER'S OFFICE 12-1-54REMARKS: Clay soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 6199 PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/3 1921

RECEIVED OF W. J. L. Lutterlin FEE OF \$ 3.00

FOR WHICH PERMISSION IS GRANTED Private

TO TAP San SEWER, ON THE W. Main

OF W. Main AVE., TYPE OF STREET Hard
ST.,

THE PREMISES BEING LOT NO. 10642-13 HOUSE NO. 1829

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Albrecht

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.