FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6205 AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-14-54	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	V	
HOUSE NO.		•	··
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	931	7'0401
WAS LATERAL AT CURET VES			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Beaves	Const
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SEF	RVED.	
			•= 9
- N		10	· .
the second secon	. Para tanàna mandritry ny taona 2001–2014. Ilay kaominina dia kaominina mpikambana amin'ny fivondrona dia kao	17 duis	
	<u> المراجعة ا</u>		. :
	بالمراد	Jr.	
	13/17/	a pagan nga na gasa aja	
	D 931		
SIGNED ROLL OF THE SERVE	FILED AT ENG	GINEER'S OFFICE	15/54
INSPECTOR FOR CIT	. Testani i i i i i i i i i i i i i i i i i i		
REMARKS:			

Nº 6205

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, 5/13/54
RECEIVED OF Blaver Instruction FEE OF 52
FOR WHICH PERMISSION IS GRANTED Steve Chellips
TO TAP Sanutary SEWER, ON THE last
of Hembral h M. AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 11100 , HOUSE NO. 754
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO 2222 BULL THE COMPANY

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR BOOMER Const. Co

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.