Nº 6218

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 808 SIZE OF PIPE USED 6 WAS LATERAL AT CURB? 125 WAS ATTACHED TO MAIN 110 SHOW BY DIAGRAM RELATION OF LATE	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR RAL TO WALL OF BUILDING SERVED.
	TALL OF BUILDING SERVED.
N . ★	Zatero
	19 olan
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 77-27-54

Nº 6218

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

The state of the s	7/2017/2019/2019/2019	the state of
	MASSILLON, OHIO, AL	1 5
RECEIVED OF a. A. Dea	na	5 110 . 12 4
FOR WHICH PERMISSION IS GRANTED WAY	and A Re	to distribution
I	A CONTRACT SECURITION OF THE CONTRACT SECURITION	
TO TAP Juni. SEWER.	ON THE	and the kind of the second
OF Stratford) E AVE. TYPE	0	ve volvo segologi V
THE PREMISES BEING LOT NO. Ph 42 329	78 , HOUSE NO. 808	<u> </u>
THE TREMPSES SERVES LEST NO.	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR (1.) Alcana

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.