Cylina R

## Nº 6227 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

		·	**
DATE INSPECTED 12-5-54	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	DISTANCE FROM FIRST MANHOLE	en e	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	28'	8 Dex10
WAS LATERAL AT CURBY	Metallica (Application of the Application of the		)
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Or. VI	emley
SHOW BY DIAGRAM RELATION OF LATER		RVED,	
			· ·
	en e	7	lup
	andrijak Teorogan Teorogan	. were the transfer of the A	(8:
	ter. Linguis Salatan Salatan Lee	erika serika di dalam da	(28')
OP I S	<u> </u>	the phase amount of the Calenda Tampa and the Labor company report of the company of the calendary of the ca	8 Olevo
SIGNED INSPECTOR FOR CIT	FILED AT EN	GINEER'S OFFICE	11
REMARKS: The hour	e is out s	ide the C	ety lime

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
6227 PERMIT TO TAP SEWER

MASSILLON, OHIO.
RECEIVED OF PER OF S
FOR WHICH PERMISSION IS GRANTED L. Eckanrole
TO TAP SEWER, ON THE
of 3rd nulave type of street 0,000
THE PREMISES BEING LOT NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC

NAME OF CONTRACTOR Remarks

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.