

Nº 6252

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-12-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 554SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 185' 8' DEEPWAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN NONAME OF CONTRACTOR P. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N. 

13' 6' deep

13' 8' deep

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8-28-54

REMARKS:

Clay Soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 6252 PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/10

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Lucile W. Carmack

TO TAP

San

SEWER, ON THE

E.

OF

27th

AVE., TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

10188

HOUSE NO.

552

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.