FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 6253 AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-13-5-4 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 157 5 19 P
WAS LATERAL AT CURBY V-65
WAS ATTACHED TO MAIN NAME OF CONTRACTOR Beaut Const
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
with the first of the state of
and the state of the second of
and the second of the second o
Port Vatta - 0 757
SIGNED FILED AT ENGINEER'S OFFICE 8 25 19 54
inger of the forest in the second profit is a factor of the second second in the second secon
NEMAINO.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER MASSILLON, OHIG, PERMIT TO TAP SEWER MASSILLON, OHIG, FEE OF \$ FOR WHICH PERMISSION IS GRANTED SEWER, ON THE OF AVE., TYPE OF STREET THE PREMISES BEING LOT NO. HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deaner Const C

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.