N9 6289

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED //- 5- 8-4	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 36'	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 1/8
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	
N. <	b'der b
SIGNED PLATANTINSPECTOR FOR CIT	on FILED AT ENGINEER'S OFFICE 12-1-54

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N_{\bullet}^{0} 6289

PERMIT TO TAP SEWER

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
MASSILLON, OHIO, 15
RECEIVED OF 1. A Deana FEE OF 5. 2"
FOR WHICH PERMISSION IS GRANTED (1.0)) = Fadden
TO TAP LUND SEWER, ON THE
OF 33, 1) 10). AVE. TYPE OF STREET STORY DELTA
THE PREMISES BEING LOT NO. $7724 - 25$, HOUSE NO. 36
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
\mathcal{O}

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.