

Nº 6295

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-10-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2229

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH STRAIGHT across from N

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Perney

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-1-54

REMARKS: Clay soil

Nº 6295

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13 1913

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Gabriel Eckenrode

TO TAP San

SEWER, ON THE P.

OF Claremont NW

AVE.
ST.

TYPE OF STREET driv

THE PREMISES BEING LOT NO. 5995

HOUSE NO. 2229

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.