Nº 6299

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-20-54 HOUSE NO. 207	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY YES	ngan menganggan pada segarah sebesah kelambangkan berhapa di peranggan berhapa selah di peranggan berhapa sebe - menganggan
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR
	The state of the s
	> Note that the state of the st
SIGNED North INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE 12-1-54
REMARKS:	C/24 801/

Nº 6299

PERMIT TO TAP SEWER

	Barer C			19/54 15
4	ION IS GRANTED	Poun bul	10 0	1
FOR WHICH PERMISSI	ON IS GRANTED	750070000	بالماروس الم	mer.
TO TAP Jane	tang	SEWER, ON T	we W	
23 101	new		TREET Oil	ecyd
THE PREMISES BEING	3718	-19	, HOUSE NO	207

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaver Construction Co

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.