FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED. AND SIGNED WHEN RETURNED.

10 11 1		•
DATE INSPECTED /2 7 7	IF SO HOW AND LOCATION FROM	
1-43	FIRST MANHOLE DOWN STREAM	
HOUSE NO.		
100	DISTANCE FROM FIRST MANHOLE CONTROL OF THE DOWN STREAM TO DITCH AT	G /
SIZE OF PIPE USED	CURB LINE AND DEPTH	<u> </u>
WAS LATERAL AT CURBY Yes	 As the desire with the desired and desired. 	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	& Pingle
SHOW BY DIAGRAM RELATION OF LATE		0 0
	and the second s	doeso
	! <u>_18</u>	e carry o
and the second of the second o	Control of the contro	÷
$\mathcal{F}_{ij} = \mathcal{F}_{ij}$		*4
real constitution of the second of the second		. 1
	The first of the second	6 deep
	The second of th	
	The second secon	A REAL PROPERTY OF THE PROPERT
00 D H		(162)
SIGNED INSPECTOR FOR CI	7 FILED AT ENGINEER'S OFFICE	
 1. Fig. 2. A part for install 	Conditionable of polynophymilatine by altern	
REMARKS:	(144 3011	

Nº 6302

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, 12/3/54 15
RECEIVED OF Under & Rangley FEE OF 502.
FOR WHICH PERMISSION IS GRANTED & Course Harteller
TO TAP LANCE TOM SEWER, ON THE
of 7 Th hw AVE TYPE OF STREET Start
THE PREMISES BEING LOT NO. 7. 178 HOUSE NO. 643
Work to be done in accordance with Ordinance No. 2323, Duly Passed by the City Council
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Walter & Blugley

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.