Nº 6304

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

. D	DATE INSPECTED 12-13-54	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
H	10USE NO. 2017		
5	IZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	5'0000
·W	VAS LATERAL AT CURBY 195	and the state of t	and the second s
	VAS ATTACHED TO MAIN		and Pringley
S	HOW BY DIAGRAM RELATION OF LATER		
		<u>4'.</u>	
- - 1,1- 2	The second of th	7 dop	5 Lep
	V	grade to the first material and an area and consection residence.	
	W .		157 >
	IGNED P. L. than	30 ELED AT ENCINEEDIS OFFI	
	INSPECTOR FOR CIT	Y STATE OF THE STA	CE.
R	EMARKS:	Granel Soil	
	· · · · · · · · · · · · · · · · · · ·		

THE STATE OF THE PROPERTY AND THE CONTROL OF PUBLIC SERVICE

PERMIT TO TAP SEWER

ing and dependence of the contract of the cont	MASSILLON, OHIO, 12/9/54 15
RECEIVED OF Ulan & P.	
FOR WHICH PERMISSION IS GRANTED	Brandt
Jan Day 1 To 1	ON THE
OF Lincoln Way E AVE. TYP	
THE PREMISES BEING LOT NO. 6/14	
Work to be done in accordance with Ordinance	E No. 2323, DULY PASSED BY THE CITY COUNCI

RULES OF THE DEPARTMENT OF PUBLIC SERVICE

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.