## Nº 6309

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-2-55	IF SO HOW AND LOCATION FROM
HOUSE NO. 2855	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  101/2 OLEAN
WAS LATERAL AT CURBY 185	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. Lana
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	10'
	Trunk 7'aup
	The state of the s
	1+3'
	42 = 3p
SIGNED VOY Athan	FILED AT ENGINEER'S OFFICE 3 76 55
REMARKS: C/ay &	forty está na sociálm si priblisti hadove do do do sociál.

## Nº 6309

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

. Ne	e renno una los propies en oblos de la colonidad. Por esta de la como en oblos de la colonidad de la colonidad.	MASSILLON, OHIO, am	ノみび
RECEIVED OF	a. J. Diano		· it miles a
e de la companya de La companya de la co	ON IS GRANTED alle	it me fac	
FOR WHICH PERMISSIO	ON IS GRANTED		
TO TAP June	stary SEWER		
of Popela	1 nw AVE. TYPI	E OF STREET dut	gensky <del>ki ys</del> jil. V
THE PREMISES BEING L		HOUSE NO. 2 F.	50
WORK TO BE DONE IN	ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY	THE CITY COUNCI

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.