Nº 6327

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4- 8	8-5-5	Tapped	4m 4 4	
DATE INSPECTED	7 D IF SO HOW AND LOCATION FROM FIRST MANHOLE DOMESTREAM	<u> </u>	511	7 <i>' D</i>
HOUSE NO. 646	UP	A Company		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	No.	To reduce the above the region.		
WAS ATTACHED TO MAIN	Ve5 NAME OF CONTRACTOR	a.d	Quina .	
SHOW BY DIAGRAM RELATIO	ON OF LATERAL TO WALL OF BUILDING SE	RVED.		Υ.
		7, Dee	, P	
and the second second	ing the second of the second o			42
		4-4-7	Tappad aus	
SIGNED POY	FILED AT EN	IGINEER'S OFFICE	6 m p m 55	#
REMARKS: S	and & Gravel so	11 72	pped	·
ate.		Ţ	• .	

Nº 6327

PERMIT TO TAP SEWER

MASSILLON, OHIO, $\frac{1}{2}$	1.5
RECEIVED OF a. J. Diana FEE OF & 9	_
FOR WHICH PERMISSION IS GRANTED	
TO TAP! Handay SEWER, ON THE	<u>.</u>
OF TINIO DE AVE. TYPE OF STREET M. C.	
THE PREMISES BEING LOT NO. 3045 , HOUSE NO. 646	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COL	INCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR A. T. W. Canal	
Γ	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.