## 6333

## THE ROLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-20-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 145 - 7 Deep
WAS LATERAL AT CURB? YES	The same fall and the control of the
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR G. Decura
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
$\stackrel{\wedge}{\sim} \mathcal{N}$	1 33' 5 occu
a um com to a concrue outside of a crass succession as a	A SANDAN CANDE TO SAND CANDELLA CANDAN CANDA
	0 10mp 1 30'
SIGNED Por STECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS:	inclinates on actionize political technology.

## Nº 6333

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/17/55-15
RECEIVED OF 9. J. Diana FEE OF 52.
La Contraction de la Contracti
FOR WHICH PERMISSION IS GRANTED WITHOUT IN THE
TO TAP fantary SEWER, ON THE
OF ohnsen & AVE. TYPE OF STREET Aut
THE PREMISES BEING LOT NO. \$255, HOUSE NO. 1020
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR 7. 1. Decemon

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.