

15-23

N^o 6335

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-21-55IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 818SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 184' 6' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NoNAME OF CONTRACTOR Urban & Pingley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

← N.

7'
48'
10'
6' deep
6' deep

SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

184' →

6-4-55

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o. 6335

PERMIT TO TAP SEWER

MASSILLON, OHIO,

4/22/55

15

RECEIVED OF

Harry Urban

FEE OF \$ 2.⁰⁰

FOR WHICH PERMISSION IS GRANTED

William Bontts

TO TAP

Sanitary

SEWER, ON THE

E

OF

Hamlock, N.W.

AVE.,
ST.,

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

11097

HOUSE NO.

818

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.