## THE RANGE OF A SECOND OF FOLLOWING DATAS TO BE ANSWERED BY INSPECTOR 6342 AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-26-55	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	İ
HOUSE NO. 1717	-	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8 Deep
WAS LATERAL AT CURB? Ves	o de la Sala Maria de la compansión de la En la compansión de la co	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	acoma
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
		5
nary i karanja napak <u>a ya kesili M</u>	and the state of t	1 Tomp
	Land of the state	70,4
SIGNED POY Lather		manus de la Contraction de La
INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE	6-4-55

## Nº 6342

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/26/55 15
RECEIVED OF A DIRAGE FEE OF S Q
FOR WHICH PERMISSION IS GRANTED Tally m Danis
FOR WHICH FERMISSION IS GRANTED
TO TAP SEWER, ON THE W
of Weyter 5) & E AVE. TYPE OF STREET gravel.
THE PREMISES BEING LOT NO. //2/2 , HOUSE NO. / 7/7
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
Rules of the Department of Public Service.
NAME OF CONTRACTOR 9 Wana

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.