Nº 6376 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-29-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	, 1
HOUSE NO. 2868	and the second s	2.1
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 96	6'Deep
WAS LATERAL AT CURB? Ves	and the second of the second o	· · · · · · · · · · · · · · · · · · ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	-gel
SHOW BY DIAGRAM RELATION OF LATER	· · · · · · · · · · · · · · · · · · ·	
n de la companya de La companya de la co	The state of the s	101
		Toler
	n in solen kolonia alaman alama ka kemili kelonian galama. Keminan alama kan salahan akan kemilik kemilik alama	46'
	in the month of the control of the control of the state of the control of the con	
		6
- 11		
SIGNED ROW Fither	FILED AT ENGINEER'S OFFICE	< -
REMARKS: ()	Hartski od vrejska ki prikile iz le slikov	

Nº 6376

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

· · · · /3 - 4//

MASSILLON, OHIO, $6/29/55$
RECEIVED OF Harry Piper FEE OF & Q. O
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
FOR WHICH PERMISSION IS GRANTED
TO TAP lanitary SEWER, ON THE
of Popelar nu AVE. TYPE OF STREET dut
The premises being lot no. 11338 , house no. 2868
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR BOGEN

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.