

Nº 6387

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~DOWN~~ STREAM

up stream
Tapped *114'* *7' x*
up

HOUSE NO. 1020

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR _____

Pemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

Peat Moss Soil

3-30 14-16
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6387

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/5

RECEIVED OF

C. A. Renchardt

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San.

SEWER, ON THE

M.

OF

Mc Mill NE

AVE., TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

P1 9/2 158

HOUSE NO.

1020

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ramsey

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.