N9 6392

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	8-18-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO.	830		
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 159	7'0000
WAS LATERAL AT CL	JR87 Yes	i Mercini, Malandini, in Mercent de estat de la celebratica de del La companya de la com	
WAS ATTACHED TO	-	- NAME OF CONTRACTOR	Lana
SHOW BY DIAGRAM	RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
	ing the state of t	di alah Milanda di Araban da salah paksas alam da salah s	
$\mathcal{N} <$		La comprese de la comprese del comprese del comprese de la comprese del comprese della comprese	7'deep
		159	140
SIGNED Port	INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	
REMARKS:	0/345		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	Massillon, Ohio,_	Aug 1	PTK 10
~ ~ ~	MASSILLON, OHIO,	7	is the second
RECEIVED OF	una.	r	EE OF S
17. 3 da w 💋 na vineda istanti. Tanan na mangalakan kanalangan at mangalakan kanalangan at kanalangan at kanalangan at kanalangan at kanalanga	· · · · · · · · · · · · · · · · · · ·		i vinto di la Billioni
FOR WHICH PERMISSION IS GRANTED	en agres	11	
Du +	() · · · · · · · · · · · · · · · · · · ·		
TO TAP SEWE	R, ON THE	<u> </u>	<u>and the strangers of t</u>
OF Thomas Circle nE AVE. TY	PE OF STREET	led	
THE PREMISES BEING LOT NO. PT 91 34			0
/			
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN	ICE No. 2323, DULY	PASSED BY T	HE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR A. J. Miano	.		
THE OF CONTINUOUS		•	*

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.