

7-22

# **FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6395 AND SIGNED WHEN RETURNED.**


DATE INSPECTED 9-7-55IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAMHOUSE NO. 826SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH123'5' DitchWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

G. Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←



SIGNED

Ray Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

clay soil

7-22  
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6395

# PERMIT TO TAP SEWER

RECEIVED OF

MASSILLON, OHIO, Sept 1st 1919

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work i  
walls of building is subject to Massillon Board of Health Regulations.