

Nº 6398

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-7-55

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 610

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 26' 7' deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR Urban & Rains

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy L. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-8-55

REMARKS: clay soil

Nº 6398

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 10th 1911

RECEIVED OF George Hastler FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED George Hastler

TO TAP Sanitary SEWER, ON THE E

OF 27th NW AVE., TYPE OF STREET dirt ST.,

THE PREMISES BEING LOT NO. PT 1/4 175, HOUSE NO. 610

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban & Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.