Nº 6414 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED. AND SIGNED WHEN RETURNED.

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 7907			
·~ ·	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	276	6'Orep
WAS LATERAL AT CURBY YES	and the second of the second second	eris e elseres e alors Elseres estatos	,
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	D. Bog	er and
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SER	VED.	
		(28,08	
1		3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
	ang Pilipina. Pang mang Kinggan nggapaggan ang panggan	7'0+10	
	e en la companya de la companya de La companya de la co	11 X - F	
		17	6'Derp
The second secon			
SIGNED Por Cathery	7. FILED AT ENG	INEER'S OFFICE	
REMARKS:	Bu ili esid oleh jilar di yai	and the second of the second o	11-10-55

Nº 6414

PERMIT TO TAP SEWER

MASSILLON, OHIO, OTT 2 1 15
RECEIVED OF Alvain Bogan FEE OF S &.
FOR WHICH PERMISSION IS GRANTED B. Bowling
FOR WHICH PERMISSION IS GRANTED
TO TAP Canitary SEWER, ON THE north
of Poplar Mul AVE. TYPE OF STREET dut
THE PREMISES BEING LOT NO. 11240 , HOUSE NO. 2902
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Diverin Bogs

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.