FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 6418 AND SIGNED WHEN RETURNED.

DATE INSPECTED //- 3 - 5	~	196AT	•
DATE INSPECTED //- 3 - 5	IF SO HOW AND LOCATION FROM		· · · · · · · · · · · · · · · · · · ·
HOUSE NO. 150			
allo a transfer of the control of th	DISTANCE FROM FIRST MANHOLE	e replicati	,
SIZE OF PIPE USED	CURB LINE AND DEPTH	209'	8 DeER
WAS LATERAL AT CURBY VES	<u>and and Applicability of the second pages as the second control of the second control o</u>	nia nimber mai	•
- 11 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			
WAS ATTACHED TO MAIN/1/O	NAME OF CONTRACTOR	Beaver Con	st Co.
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVE	ɔ.	
un de la companya de de la companya de la companya La companya de la co			
	The state of the s	an an was a sumurawa masa meningga kanala da an angangga kanala da an angangga kanala da an angangga kanala da Mangangga kanala da angangga kanal	7'
			7'Deep
areas from a record of the second	<u>and</u> Appropriate to the first and the control of t		04
	The second of Lorentz States and the second of the second	Common order to ector	41
		7	
\sim 10 $^{\circ}$	0	209'	
SIGNED NON Follow	FILED AT ENGINE	TER'S OFFICE	3-56
INSPECTOR F	or city isola invitava ilaliot itolidina si jenilili		
REMARKS:	and the common terms of the most of the second of the seco	· · · · · · · · · · · · · · · · · · ·	<u> </u>

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

en e
MASSILLON, OHIO,19
RECEIVED OF Blaver Grangting to FEE OF \$ 2"
FOR WHICH PERMISSION IS GRANTED Comil Coming
TOTAP Sanitary SEWER, ON THE last
OF 2 + US W AVE., TYPE OF STREET dist
THE PREMISES BEING LOT NO. 3779 , HOUSE NO. 150
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council

NAME OF CONTRACTOR Beaver Excavity G.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.