Nº 6435

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 5-27-5-5 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | | |
|--|---|--------------------------------|-------------|
| HOUSE NO. 237 | | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | 47' | 7'000 |
| WAS LATERAL AT CURB? YES | | a trace characteristic control | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR | R. Rum | ley |
| SHOW BY DIAGRAM RELATION OF LATER | RAL TO WALL OF BUILDING SER | VED. | <i>(</i> |
| A superior of the second control of the second contro | | 3 | |
| | | 00 | |
| a aktir ya toga en tali diperenara da iniba basa p Angara penangan angara Angara | alia pergrapa di salah direngah berah di bada Silah sebesah di salah dan di sebesah di seb Sebesah di sebesah | 36 | |
| \mathcal{N} | | 15: | |
| p. Q. | and the second of the second o | 777 | |
| SIGNED JOY Yatha | FILED AT ENG | INEER'S OFFICE | → |
| /INSPECTOR FOR CIT | ne Majaki ce tingder si Nei | istantina tina | - 2 2 - 5 5 |

Nº 6435

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | Massillon, Ohio | o. <i>//-2 9 - 5</i> 519. |
|--|-----------------|--------------------------------|
| RECEIVED OF Propries | and Remoen | FEE OF 5 |
| FOR WHICH PERMISSION IS GRANTED | O L | |
| TO TAP Danitary | | |
| or Oak Sui | AVE. | an word |
| THE PREMISES BEING LOT NO. | | |
| | | |
| WORK TO BE DONE IN ACCORDANCE WIT RULES OF THE DEPARTMENT OF PUBLIC S | | ULT PASSED BY THE CITY COUNCIL |
| NAME OF CONTRACTOR 12 Re | mo. | |
| | | lding only. Any work in |

walls of building is subject to Massillon Board of Health Regulations.