Nº \_6454

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SÍGNED WHEN RETURNED

DATE INSPECTED 3-9-5-6	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2237	
SIZE OF PIPE USED6" v	POISTANCE FROM FIRST MANHOLE POWN STREAM TO DITCH AT TOPPED 193 UPSTREBNAM CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	radio de la composição de La composição de la compo
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR A DIZAZ
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	à jui
	we miny
SIGNED Por Fatham	FILED AT ENGINEER'S OFFICE 5-4-56
INSPECTOR FOR CIT	

## Nº 6454

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	i de la companya de La companya de la co	ASSILLON, OHIO, TH	(l 27 19
RECEIVED OF	a. Dian		FEE OF \$
	GRANTED Mich		
	SEWER		4、1946年, 4、1967年, 4、1967年, 4、1967年, 40年, 40年, 40年,
or	AVE. ST. TYPE (	OF STREET PA	vegle
THE PREMISES BEING LOT	vo. # / 0350	, HOUSE NO.	
WORK TO BE DONE IN ACC	CORDANCE WITH ORDINANCE IT OF PUBLIC SERVICE.	: No. 2323, DULY PAS	SED BY THE CITY COUNCIL
Name of Contractor	a. & Dian		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.