## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-10-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 919			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	200'	7' Deer
WAS LATERAL AT CURB? Yes	<ul> <li>transfer in the first transfer in the second section of the second second</li></ul>		
WAS ATTACHED TO MAIN //O	NAME OF CONTRACTOR	Vilona	= Pingley
SHOW BY DIAGRAM RELATION OF LA	ATERAL TO WALL OF BUILDING SE	RVED.	TT
		<b>4</b>	
		7de	p
many the management of the second states of		V6'	
			.p
		10' 10e	eP [
P. 10.		2	00'
SIGNED INTEREST FOR	FILED AT EN	GINEER'S OFFICE	The second secon
REMARKS			9-11-56

Nº 6458

No 6458 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

ing district of The Samples		erina e la desperimente de la la despera Valenta de la como e la calenda de la c	Massill	ON, OHIO, 🧌	lack	<del>) (/_ 19</del>
	RECEIVED OF	Deir R R				
and the second	in the Artiflet in graphings in	IS GRANTED	医细胞性阴极性 医肾上腺	and the state of the contract	and the second second	
1 1			and fig. 1	de care facilitate por un un deficiel (1777)	医毛术 阿拉克洛弗特斯氏虫	
TO TAP	12.7		$\underline{\hspace{0.1cm}}^{\hspace{0.1cm} \hspace{0.1cm}}$ sewer on th	E(	<u> </u>	
A STATE		Tylen.				
THE PR	EMISES BEING LO	т no. <i>(С+</i> 995)	-32	, HOUSE NO	919	
WORK	TO BE DONE IN	ACCORDANCE WITH C	ORDINANCE NO. 2	2323, DULY PAS	SED BY THE (	CITY COUNCIL
Rules	OF THE DEPARTM	MENT OF PUBLIC SERV	ICE.			
NAME	OF CONTRACTOR	1/1/1/2 6	Kinden			
			A = A			
jih ji (	Note $This$	permit covers w	ork outside	of building	only. An	y work in
walls	of building	is subject to Ma	ssillon Boar	d of Health	Regulatio	ns.