Nº \_6463

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $3-19-56$	IF SO HOW AND LOCATION FROM 101
HOUSE NO. 1910	
SIZE OF PIPE USED $a^n$	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY WO	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR (NUebel)
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	7óccp
	- 60° - 13' - 10', -
SIGNED Por Lothan	Side Walk
(NSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
海上医疗医院医疗 经国际基金证券 医多克氏菌 经销售的 医白	

## Nº 6463

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,_	Morch 13 10
RECEIVED OF	O. Welen	FEE OF \$ 5 C
	Jack Laurence	그리 그는 그렇다는 그리고 있는 그리고 하는 경기를 즐겁다.
TO TAP O POST MAN	하는 지난 사람들은 그 그 가는 사람들이다.	
THE PREMISES BEING LOT NO. 504	House	NO. 1911
WORK TO BE DONE IN ACCORDANCE WITH		전문 발표를 보고 있다. 그 등로 교통를
RULES OF THE DEPARTMENT OF PUBLIC S	医二类性连续连接 医动物动物 医多异性医肠切除的	
NAME OF CONTRACTOR POLICE	1) sher	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.