

No 6467

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3- -56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1023

SIZE OF PIPE USED 6" UP ~~DOWN~~ STREAM TO DITCH AT
CURB LINE AND DEPTH 76' upstream NH. 7'


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No


NAME OF CONTRACTOR

Urban & Pungley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



up stream
NH.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-4-56

REMARKS

Nº 6467

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 29 1919

RECEIVED OF

Harry Wilson

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED

D. J. Ringorick

TO TAP

sanitary

SEWER ON THE

west

OF

14th SW

AVE.

ST. TYPE OF STREET

slit

THE PREMISES BEING LOT NO.

8938

HOUSE NO.

1022

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Wilson & Ringorick

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.