

Relay
N^o 6476

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-20-56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Tapped 202' 8' D.

HOUSE NO. 735

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

P. Pernley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



*Relay
48'*

0 202'

48'
8'
50' up

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-4-56

REMARKS

Relay

Nº 6476

Relief

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 5th*, 19

RECEIVED OF *Raymond Remley* FEE OF \$ *2⁰⁰*

FOR WHICH PERMISSION IS GRANTED *Martha Thomas*

TO TAP *sanitary* SEWER ON THE *West*

OF *Erie St.* AVE. TYPE OF STREET *graded*

THE PREMISES BEING LOT NO. *9383-B*, HOUSE NO. *735*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Raymond Remley*

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.