Nº \_6489

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $\frac{9-19-6}{}$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2/33		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	810-4-610
WAS LATERAL AT CURB? Yes		
WAS ATTACHED TO MAIN	— NAME OF CONTRACTOR 4	Desing.
SHOW BY DIAGRAM RELATION OF LA	ATERAL TO WALL OF BUILDING SERVED.	
		1/0
		1/7'neef
	$\forall$	
	Jac.	er/5 <sup>2</sup>
	$\bigvee$	/al
SIGNED Por fall	FILED AT ENGINEER'S OFFICE	
/ INSPECTOR FOR	CITY	
REMARKS		

## Nº 6489

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLO	N, OHIO, 4/19/57	19
RECEIVED OF	Ma Diana	N, OHIO, 4//19/57 FEE OF \$ 0	2, 04
FOR WHICH PERMISSION IS GRA	NTED UCE Youle		
TO TAP CAME TALL	SEWER ON THE	bout	
of Clarenon H.	AVE. TYPE OF STREE	er caled	
	6030-6031		
WORK TO BE DONE IN ACCOR	化海绵电流 化电流流 化二甲酚 医二氏性神经 医克勒氏管 电电流电流 电电流	323, DULY PASSED BY THE CITY CO	UNCIL
NAME OF CONTRACTOR	1 Diana		
	it covers work outside o bject to Massillon Board	of building only. Any world of Health Regulations.	k in