N? _6516

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED
HOUSE NO
SIZE OF PIPE USED DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?
WAS ATTACHED TO MAIN Y-es NAME OF CONTRACTOR BEN HANDEY LOID STUCKFOR I
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
50 /28
SIGNED FILED AT ENGINEER'S OFFICE
REMARKS

Nº 6516

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, Line 2/15
RECEIVED OF
FOR WHICH PERMISSION IS GRANTED Mich Oyoland
TO TAP No Montale sewer on the can't
OF Cleveland Stude Type OF STREET Shit
THE PREMISES BEING LOT NO. 4/7) F. HOUSE NO. 1/10
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR OF DECEMBER OF CONTRACTOR
Note This permit covers work outside of building only. Any work is

walls of building is subject to Massillon Board of Health Regulations.