FOLLO	WING DATA TO BE ANSWERED BY INSPECTOR
Nº 6517	AND SIGNED WHEN RETURNED
, 1,4	
DATE INSPECTED 4-6-5 (	IF SO HOW AND LOCATION FROM Relay From Cub to 1
HOUSE NO. 1104	FIRST MANHOLE DOWN STREAM VILLEY THON LUNE TO /
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY YES	
WAŞ ATTACHED TO MAIN NO	— NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
	프로그램 전환 기계 등 수 있는 것도 보면 함께 되었다. 그는 그를 보고 있는 것이 되었다. 그는 것이 되었다. 그는 것이 되었다. 그는 것이 하고 있는 것이 된 것이 되었다. 그는 것이 되었다. 그는 것이 되었다. 그는 것이 되었다. 그는 것이 되었다.
$N \leftarrow -$	T7/2 dup
	1.12. \_8 dup
	East Curo.
SIGNED Por fat	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOI	R CITY:
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6517 Reloy

## PERMIT TO TAP SEWER

	MASSILLON, OHIO, 21 19
RECEIVED OF	FEE OF \$ 2
	Leong Orighan
TO TAP DA - TA	SEWER ON THE
of 17th US	AVE. ST. TYPE OF STREET MM. C.
	G HOUSE NO. // 0 4/
WORK TO BE DONE IN ACCORDANCE WIT RULES OF THE DEPARTMENT OF PUBLIC S	TH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
그는 사람들이 되어 되었다. 그런 경우를 받는 것을 가는 것을 다. 사람들이 되고 있는 것이 되었다. 그런 그런 그런 그런 그런 것이다.	
NAME OF CONTRACTOR	D. ana

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.