

N<sup>o</sup> 6534

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-56 IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 1814

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT 130'  
CURB LINE AND DEPTH 7' De

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR P. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Prof Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 130'

REMARKS \_\_\_\_\_

11-15-56

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6534

## PERMIT TO TAP SEWER

MASSILLON, OHIO,

7/7/56

19.

RECEIVED OF

Raymond Remley

FEE OF \$

2<sup>00</sup>

FOR WHICH PERMISSION IS GRANTED

John Baker

TO TAP

Sanitary

SEWER ON THE

north

OF

Vermont Ave 18<sup>th</sup>

AVE.

ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

6172

HOUSE NO.

1814

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note This permit covers work outside of building only. Any work in  
walls of building is subject to Massillon Board of Health Regulations.